Document generated on: July 26, 2022, 04:44:28(UTC+1)

#### After Picture

### Overview

PCN	Resin Material	Molex Description	
512360	Retraction PCN	PCN#509831  Add additional manufacturing location for 52852 housing. The reason for the change is to secure the supply for 52852 housing at Molex Malaysia	

- After additional review, Molex Malaysia is revising the decision to retract part numbers from PCN#509831 due to Molex Malaysia decided not to sub-out the mold (housing) to vendor.
- No changes will be made to the part numbers stated in this retraction.



You may address inquires regarding this PCN by clicking on the below link mailto:pcn\_coordinator@molex.com?subject=PCN\_Notification:512360 or contact your Local Sales Engineer.

Note: While responding, please retain "PCN Notification: PCN Notification: 512360" in the e-mail Subject line for faster response.

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL (800) 786-6539 www.molex.com

PCN No	Part List
512360	528520470
512360	528520472
512360	528520570
512360	528520670
512360	528520770
512360	528520870
512360	528520970
512360	528520974
512360	528521070
512360	528521170
512360	528521270
512360	528521370
512360	528521470
512360	528521472
512360	528521570
512360	528521670
512360	528521870
512360	528521970
512360	528522070
512360	528522270
512360	528522370
512360	528522470
512360	528522570
512360	528522670
512360	528522770
512360	528522870
512360	528522970
512360	528523070



# **Product Change Notification (PCN)**

PCN Number | 509831 Date Issued | September 21, 2021

Reason for Change | Equipment Transfer, Production Transfer or Rearrangement

Change Type Descrip This letter is to inform you that production of the part(s) identified in this notice is being moved to a different production location. No changes will be made to the product as a result of this move.

leason for Short Notice

Assessment of Change

New Capacity

First article inspection

Internal Molex Qualification Date

November 12, 2021

Sample Availability Date (Changed Part)

November 12, 2021

Planned Implementation Date

December 29, 2021

Method of Identifying Change

Date code

#### Before Change

#### Overview

 Insufficient capacity for 52852 housing manufacturing in Molex Malaysia and to secure the supply for 52852 series housing.

## After Change

Overview

 The purpose of this letter is to add additional manufacturing location for 52852 housing. The reason for the change is to secure the supply for 52852 housing at Molex Malaysia.

Part Number	Before	After
52852 Series	Molex Malaysia	Molex Malaysia and Subcon Malaysia

- Molex Malaysia Part Number(s) Affected
- Refer to attached for the impacted parts
- Product Impact
  - There is no impact of the change since there is no change in design, process on the mold therefore no change in the Molex assembly part number will occur either.
- Qualification Reports and samples available upon request



# **Product Change Notification (PCN)**

You may address any technical inquiries regarding this PCN by sending E-mail to pcn\_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "PCN Notification:509831" in the e-mail Subject line for faster response.

# RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com PCN # Molex Part # 509831 528521070 509831 528520670