



Product Change Notification

Current Date: 22-Aug-2022

TE Connectivity

Product Change Notification: P-22-023216

PCN Date: 19-AUG-22

Customer: Heilind Electronics Inc(0002135900)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Various Materials (Same Dual Source)

Description of Changes

Affects customers purchasing from TE North America only. Adding TE-Suzhou, China for alternate manufacturing source. PN is currently in series production at that location. Materials: PLG, 12P, GRY, N, A PLG, 4P, GRY, N PLG, 12P, GRY, N, SEAL RET, ENH KEY, A PLG, 4P, GRY, E PLG, 12P, GRY, E, A REC, 3P, BLK, E, XCAP REC, 4P, BLK, N UMNL SOK 20-14 .0126 PTPBR SOC, SF, SIZE 16, 14-18, NI/SN CLIP, SS, 11MM HOLE, ST CLIP, SS, 11MM HOLE, ST, DT8PIN CLIP, STEEL, ZINC, 8.2MM HOLE, ST,DT8PIN MICRO MNL RPT CNT STRIP 20-24 UMNL PIN 20-14 .0126 PTPBR Carrier, 26P GenerationY, Hand Mate Conn CLIP, STEEL, ZINC, 8.2MM HOLE, SIDE

Reason for Changes:

Products improvements. Additional parts source to improve delivery constraints.

Estimated Dates:

| | |
|---|---|
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): |
| | 01-SEP-2022 |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |
| | No Mixed Shipments |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| 1027-003-1200 | NO | | | "ZPF00000000139328" | | | |
| 1062-14-0122 | NO | | | "ZPF00000000131928", "1062-14-0122-LD", "1062-14-0122-LS", "1062-14-0122-E", "1062-14-0122-L" | | | |
| 350536-1 | NO | | | "403429822" | | | |
| 350538-1 | NO | | | "CU3084-000", "AMPS-0-0350538-1" | | | |
| 794606-1 | NO | | | "AMPS-0-0794606-1", "F30642-000" | | | |
| DT04-3P-CE09 | NO | | | | | | |
| DT04-4P-E004 | NO | | | | | | |
| DT06-12SA | NO | | | | | | |
| DT06-12SA-C015 | NO | | | | | | |
| DT06-4S | NO | | | "2-1899779-3", "EH7682-000", "DE-DT06-4S", "8202606747" | | | |

Customer: Heilind Electronics Brasil Ltda (3088064)

Location: Sao Paulo

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------------|---------------------------|------------------|----------------------|----------------------------------|------------------------|---------------------------------|---------------------------|
| 350536-1 | NO | | | "403429822" | | | |
| 794606-1 | NO | | | "AMPS-0-0794606-1", "F30642-000" | | | |

Customer: Heilind Electronics Inc (3181260)

Location: Mentor

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------------|---------------------------|------------------|----------------------|----------------------------------|------------------------|---------------------------------|---------------------------|
| 350536-1 | NO | | | "403429822" | | | |
| 350538-1 | NO | | | "CU3084-000", "AMPS-0-0350538-1" | | | |
| 794606-1 | NO | | | "AMPS-0-0794606-1", "F30642-000" | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|------------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| DT04-3P-CE09 | NO | | | | | | |
| DT04-4P-E004 | NO | | | | | | |
| DT06-12SA | NO | | | | | | |
| DT06-4S | NO | | | "2-1899779-3", "EH7682-000", "DE-DT06-4S", "8202606747" | | | |

Customer: Heilind Asia Pacific (SG) Pte Ltd (3076161)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 350536-1 | NO | | | "403429822" | | | |

Customer: Maverick Electronics (3142125)

Location: Mcallen

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| DT06-4S | NO | | | "2-1899779-3", "EH7682-000", "DE-DT06-4S", "8202606747" | | | |

Customer: Heilind Electronics Inc (3144575)

Location: Mcallen

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 350536-1 | NO | | | "403429822" | | | |

Customer: Heilind Electronics Inc (167811)

Location: Wilmington

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| 1027-003-1200 | NO | | | "ZPF00000000139328" | | | |
| 350536-1 | NO | | | "403429822" | | | |
| 350538-1 | NO | | | "CU3084-000", "AMPS-0-0350538-1" | | | |
| 794606-1 | NO | | | "AMPS-0-0794606-1", "F30642-000" | | | |
| DT04-3P-CE09 | NO | | | | | | |
| DT04-4P-E004 | NO | | | | | | |
| DT06-12SA | NO | | | | | | |
| DT06-4S | NO | | | "2-1899779-3", "EH7682-000", "DE-DT06-4S", "8202606747" | | | |

Customer: Heilind Asia Pacific (3133470)

Location: Shanghai

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 350536-1 | NO | | | "403429822" | | | |

Customer: Heilind Electronics, Inc., D.B. (3147483)

Location: Rosenheim

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| 1062-14-0122 | NO | | | "ZPF00000000131928", "1062-14-0122-LD", "1062-14-0122-LS", "1062-14-0122-E", "1062-14-0122-L" | | | |
| DT06-12SA-C015 | NO | | | | | | |
| DT06-4S | NO | | | "2-1899779-3", "EH7682-000", "DE-DT06-4S", "8202606747" | | | |

Customer: Heilind Electronics Inc (1275266)

Location: Visalia

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| 1027-003-1200 | NO | | | "ZPF00000000139328" | | | |
| 350536-1 | NO | | | "403429822" | | | |
| 350538-1 | NO | | | "CU3084-000", "AMPS-0-0350538-1" | | | |
| 794606-1 | NO | | | "AMPS-0-0794606-1", "F30642-000" | | | |
| DT06-4S | NO | | | "2-1899779-3", "EH7682-000", "DE-DT06-4S", "8202606747" | | | |

Customer: Heilind Asia Pacific (Hong Kong) (2980376)

Location: Shatin, N.t.

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------------|---------------------------|------------------|----------------------|----------------------------------|------------------------|---------------------------------|---------------------------|
| 350536-1 | NO | | | "403429822" | | | |
| 350538-1 | NO | | | "CU3084-000", "AMPS-0-0350538-1" | | | |
| 794606-1 | NO | | | "AMPS-0-0794606-1", "F30642-000" | | | |

Customer: Maverick Electronics (1336962)

Location: Wilmington

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| DT06-4S | NO | | | "2-1899779-3", "EH7682-000", "DE-DT06-4S", "8202606747" | | | |

Customer: Heilind Electronics Inc (3181260)

Location: Mentor

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|------------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| 350536-1 | NO | | | "403429822" | | | |
| 350538-1 | NO | | | "CU3084-000", "AMPS-0-0350538-1" | | | |
| 794606-1 | NO | | | "AMPS-0-0794606-1", "F30642-000" | | | |
| DT04-3P-CE09 | NO | | | | | | |
| DT04-4P-E004 | NO | | | | | | |
| DT06-12SA | NO | | | | | | |
| DT06-4S | NO | | | "2-1899779-3", "EH7682-000", "DE-DT06-4S", "8202606747" | | | |

Customer: Heilind Electronics Inc (1276409)

Location: Plano

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| 350536-1 | NO | | | "403429822" | | | |

Customer: Heilind Electronics Inc (167811)

Location: Wilmington

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| 1027-003-1200 | NO | | | "ZPF00000000139328" | | | |
| 350536-1 | NO | | | "403429822" | | | |
| 350538-1 | NO | | | "CU3084-000", "AMPS-0-0350538-1" | | | |
| 794606-1 | NO | | | "AMPS-0-0794606-1", "F30642-000" | | | |
| DT04-3P-CE09 | NO | | | | | | |
| DT04-4P-E004 | NO | | | | | | |
| DT06-12SA | NO | | | | | | |
| DT06-4S | NO | | | "2-1899779-3", "EH7682-000", "DE-DT06-4S", "8202606747" | | | |

Customer: Heilind Electronics Inc (2873182)

Location: Plano

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------------|---------------------------|------------------|----------------------|----------------------------------|------------------------|---------------------------------|---------------------------|
| 350538-1 | NO | | | "CU3084-000", "AMPS-0-0350538-1" | | | |

Customer: Heilind Asia Pacific (Hong Kong) (2991513)

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------------|---------------------------|------------------|----------------------|----------------------------------|------------------------|---------------------------------|---------------------------|
| 350536-1 | NO | | | "403429822" | | | |
| 350538-1 | NO | | | "CU3084-000", "AMPS-0-0350538-1" | | | |
| 794606-1 | NO | | | "AMPS-0-0794606-1", "F30642-000" | | | |

Customer: Heilind Electronics GmbH (3050932)

Location: Rosenheim

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------------|---------------------------|------------------|----------------------|----------------------------------|------------------------|---------------------------------|---------------------------|
| 350536-1 | NO | | | "403429822" | | | |
| 794606-1 | NO | | | "AMPS-0-0794606-1", "F30642-000" | | | |

Customer: Heilind Electronics, Inc., D.B. (1202905)

Location: Feldkirchen-Westerham

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------------------|---------------------------|------------------|----------------------|---|------------------------|---------------------------------|---------------------------|
| 1062-14-0122 | NO | | | "ZPF00000000131928", "1062-14-0122-LD", "1062-14-0122-LS", "1062-14-0122-E", "1062-14-0122-L" | | | |
| DT06-12SA-C015 | NO | | | | | | |
| DT06-4S | NO | | | "2-1899779-3", "EH7682-000", "DE-DT06-4S", "8202606747" | | | |

