

## Amphenol Canada Corp - Cisco Product Change Notice (PCN)

PCN Date	November 20, 2023
Supplier Name:	Amphenol Canada Corporation
Amphenol Canada PCN Number	PCN-C05034
Description of Change	Transfer of production of RJ products from Shenzhen, China factory to Cochin, India factory.
Reason for Change	Operational strategy.
Summary of changes between new and old part	The manufacturing location is the only change, the parts will be equivalent. This PCN is intended to provide advance notice to Amphenol's customers so that they can order sufficient buffer stock to avoid production delays during the transfer period. Exact part number based PCN will follow as a revision to this PCN.
Traceability guidelines (lot code / date code, markings, ship date...)	Products shipped with production lot code 2418* and later will be manufactured in Cochin, India. *PCN effectivity date subject to change, please contact an Amphenol representative with any questions.
Last Time Buy Date	This is a running change. The complete transfer of the manufacturing location will take approximately 3 months during which there will be no production of parts.
Datasheet attached? & Filename(s)	
Qual Test data attached? & Filename(s)	Please refer to <a href="http://www.amphenol-cs.com">www.amphenol-cs.com</a> or consult an Amphenol representative.

Customer Part number	Amphenol Series	Amphenol Part Number ( "X" Denotes all available options for that particular position in the part number )	PCN Effectivity Date	Samples Availability Date	Last Time Buy Date	Expected Supplier Qual Date
	RJCSE	RJCSE-XX8X-XX				
	RJE01	RJE01-1XX-0XX				
	RJE01	RJE01-6XX-0XX				
	RJE01	RJE01-GXX-0XX				
	RJE01	RJE01-JXX-0XX				
	RJE23	RJE23-166-0X1XT				
	RJE23	RJE23-188-0X1XT				
	RJE23	RJE23-188-1X1XT				
	RJE23	RJE23-188-2X1XT				
	RJE23	RJE23-188-3X1XT				
	RJE37	RJE37-188-XXXX				
	RJE3A	RJE3A-188-XXXX				
	RJE3B	RJE3B-188-XXXX				
	RJE3C	RJE3C-188-XXXX				
	RJE48	RJE48-188-XXXX				
	RJE48	RJE48-288-XXXX				
	RJE48	RJE48-488-XXXX				
	RJE49	RJE49-188-XXXX				
	RJE50	RJE50-188-XXXX				
	RJE58	RJE58-188-XXXX				
	RJE58	RJE58-488-XXXX				
	RJE59	RJE59-188-XXXX				
	RJE60	RJE60-188-XXXX				
	RJE71	RJE71-188-XXXX				
	RJE72	RJE72-188-XXXX				
	RJE72	RJE72-288-XXXX				
	RJE72	RJE72-488-XXXX				
	RJE73	RJE73-188-XXXXX				
	RJE7A	RJE7A-188-XXXX				
	RJE88	RJE88-188-XXXX				
	RJESE	RJESE-7X6X-01	01-May-24			
	RJESE	RJESE-8X8X-01	Lot codes 2418 and later.	01-Mar-24	N/A	01-May-24
	RJESE	RJESE-8X8X-02				
	RJESE	RJESE-8X8X-04				
	RJHSR	RJHSE-3X8X				
	RJHSE	RJHSE-5X8X				
	RJHSE	RJHSE-5X8X-02				
	RJHSE	RJHSE-5X8X-04				
	RJHSE	RJHSE-5X8X-06				
	RJHSE	RJHSE-5X8X-08				
	RJHSE	RJHSE-7X6X				
	RJHSE	RJHSE-7X6X-02				
	RJHSE	RJHSE-7X6X-04				
	RJHSE	RJHSE-7X6X-06				
	RJHSE	RJHSE-7X6X-08				
	RJHSE	RJHSE-EX8X				
	RJHSE	RJHSE-EX8X-02				
	RJHSE	RJHSE-EX8X-04				
	RJHSE	RJHSE-EX8X-06				
	RJHSE	RJHSE-EX8X-08				
	RJHSE	RJHSE-GX8X				
	RJHSE	RJHSE-GX8X-02				
	RJHSE	RJHSE-GX8X-04				
	RJHSE	RJHSE-GX8X-06				
	RJHSE	RJHSE-GX8X-08				
	RJHSE	RJHSE-JX8X				
	RJHSE	RJHSE-JX8X-02				
	RJHSE	RJHSE-JX8X-04				

## Amphenol Canada Corp - Cisco Product Change Notice (PCN)

PCN Date	November 20, 2023					
Supplier Name:	Amphenol Canada Corporation					
Amphenol Canada PCN Number	PCN-C05034					
Description of Change	Transfer of production of RJ products from Shenzhen, China factory to Cochin, India factory.					
Reason for Change	Operational strategy.					
Summary of changes between new and old part	The manufacturing location is the only change, the parts will be equivalent. This PCN is intended to provide advance notice to Amphenol's customers so that they can order sufficient buffer stock to avoid production delays during the transfer period. Exact part number based PCN will follow as a revision to this PCN.					
Traceability guidelines (lot code / date code, markings, ship date...)	Products shipped with production lot code 2418* and later will be manufactured in Cochin, India. *PCN effectivity date subject to change, please contact an Amphenol representative with any questions.					
Last Time Buy Date	This is a running change. The complete transfer of the manufacturing location will take approximately 3 months during which there will be no production of parts.					
Datasheet attached? & Filename(s)	Please refer to <a href="http://www.amphenol-cs.com">www.amphenol-cs.com</a> or consult an Amphenol representative.					
Qual Test data attached? & Filename(s)						
	RJHSE	RJHSE-JX8X-06	01-May-24  Lot codes 2418 and later.	01-Mar-24	N/A	01-May-24
	RJHSE	RJHSE-JX8X-08				
	RJHSR	RJHSE-NX8X				
	RJHSR	RJHSE-VX8X				
	RJHSR	RJHSR-5X8X				
	RJHSR	RJHSR-5X8X-02				
	RJHSR	RJHSR-5X8X-04				
	RJHSR	RJHSR-5X8X-06				
	RJHSR	RJHSR-5X8X-08				
	RJHSR	RJHSR-7X6X				
	RJHSR	RJHSR-7X6X-02				
	RJHSR	RJHSR-7X6X-04				
	RJHSR	RJHSR-7X6X-06				
	RJHSR	RJHSR-7X6X-08				
	RJHSR	RJHSR-EX8X				
	RJHSR	RJHSR-EX8X-02				
	RJHSR	RJHSR-EX8X-04				
	RJHSR	RJHSR-EX8X-06				
	RJHSR	RJHSR-EX8X-08				
	RJHSR	RJHSR-GX8X				
	RJHSR	RJHSR-GX8X-02				
	RJHSR	RJHSR-GX8X-04				
	RJHSR	RJHSR-GX8X-06				
	RJHSR	RJHSR-GX8X-08				
	RJHSR	RJHSR-JX8X				
	RJHSR	RJHSR-JX8X-02				
	RJHSR	RJHSR-JX8X-04				
	RJHSR	RJHSR-JX8X-06				
	RJHSR	RJHSR-JX8X-08				
	RJLSE	RJLSE4XX8X01X				
	RJLSE	RJLSE6XX6X01X				
	RJSAE	RJSAE-XX8X-X2X				
	RJSAE	RJSAE-XX8X-X4X				
	RJSAE	RJSAE-XX8X-X8X				
	RJSBE	RJSBE-XX8X-C1X				
	RJSBE	RJSBE-XX8X-C2X				
	RJSBE	RJSBE-XX8X-C4X				
	RJSSE	RJSSE-XX8X				
	RJSSE	RJSSE-XX8X-01T				
	RJSSE	RJSSE-XX8X-02X				
	RJULE	RJULE-4XX8X-XX				